
MALAYSIA

PHONE: 6-03-8529 1318
FAX: 6-03-8529 1310
Email ais@caam.gov.my
URL: aip.caam.gov.my

CIVIL AVIATION AUTHORITY OF MALAYSIA
AERONAUTICAL INFORMATION SERVICES
LEVEL 2, WEST WING TERMINAL NORTH
JALAN CTA 3
KUALA LUMPUR INTERNATIONAL AIRPORT
64000 KLIA, SEPANG,
SELANGOR DARUL EHSAN

**AIRAC AIP SUP
61/24**
**Effective Date: 28 NOV 2024
until 27 MAY 2025**
Publication Date: 17 OCT 2024

**KUCHING INTERNATIONAL AIRPORT (WBGG)
RUNWAY GUARD LIGHT UNSERVICEABLE**

1 INTRODUCTION

- 1.1 This AIRAC AIP Supplement is to inform all concerned about the unserviceability of the runway guard light until 27th May 2025.

WBGG AD 2.9 SURFACE MOVEMENT GUIDANCE AND CONTROL SYSTEM AND MARKINGS

3	Stop bars and runway guard lights (if any)	Runway guard lights for TWY A, A2 and C are unserviceable due to maintenance works
---	--	--

WBGG AD 2.20 LOCAL AERODROME REGULATIONS (ADDITIONAL)

- 2.20.7 Pilots are advised to exercise caution when taxiing on the taxiways.

2 VALIDITY

- 2.1 This AIRAC AIP Supplement will remain in force until 27th May 2025. Any updates, changes and cancellations to this AIRAC AIP Supplement will be notified through NOTAM.

- END -