
MALAYSIA

PHONE: 6-03-8529 1318
FAX: 6-03-8529 1310
Email ais@caam.gov.my
URL: aip.caam.gov.my

CIVIL AVIATION AUTHORITY OF MALAYSIA
AERONAUTICAL INFORMATION SERVICES
LEVEL 2, WEST WING TERMINAL NORTH
JALAN CTA 3
KUALA LUMPUR INTERNATIONAL AIRPORT
64000 KLIA, SEPANG,
SELANGOR DARUL EHSAN

**AIRAC AIP SUP
67/24**
**Effective Date: 26 DEC 2024
to UFN**
Publication Date: 14 NOV 2024

**KUALA LUMPUR INTERNATIONAL AIRPORT (WMKK)
STOPBAR LIGHTS AND LEAD IN LIGHT
TAXIWAY A1-A11, C1-C11, P1-P4, Q5-Q7 AND Y1-Y9**

1 INTRODUCTION

- 1.1 This AIRAC AIP Supplement is to inform all concerned about the unavailability of the STOPBAR LGT AND LEAD IN LGT FM INT A1-A11, INT C1-C11, INT P1-P4, INT Q5-Q7 AND INT Y1-Y9 until further notice.
- 1.2 Runway Guard Lights are available for operational use.
- 1.3 Pilot to exercise caution during entering runway.

2 VALIDITY

- 2.1 This AIRAC AIP Supplement supersedes NOTAM A4452/24, A4453/24, A4454/24, A4455/24 and will remain in force until further notice. Any updates, changes and cancellation to this AIRAC AIP Supplement will be notified through NOTAM.

- END -